Miller Creek Greenway Concept Report








APPENDIX

B



Photo ID: 006
Location: S 138th St and 9th PL
Description: Roadside ditch and culverts. Piped drainage to vegetated ditches on 10th Ave. Between 137th and 138th Street, driveway culverts with ditches. Piped conveyance on East side of street.

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.



Photo ID: 011
Location: S 138th St and 10th Ave
Description: Ditched conveyance at 10th Ave.

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.



Photo ID: 015
Location: S 138th St and 10th Ave
Description: Ditch conveyance with driveway culverts on both sides of 10th Ave. Piped storm on west side of street.

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.



Photo ID: 022
Location: S 138th St and 11th PL (Facing North)
Description: City of Burien Stormwater facility to reduce downstream flooding and improve water quality. Control structure located at SE corner.
Observations: Drains cul-de-sac development.



Photo ID: 024
Location: S 138th St and 11th PL (Facing South)

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.

Description: City of Burien Stormwater flow control structure with riser. This facility discharges on to the NERA project limits.



Photo ID: 030
Location: Airport parking lot called Ajax Parking (Facing West)
Description: New arch culvert under a bridge for the new parking lot. The parking lot also has 2 Contech Stormwater treatment vaults.



Photo ID: 031
Location: Miller Creek Wetland adjacent to Airport parking lot (Facing NW)
Description: Miller Creek U/S wetland
Observations: U/S wetland is served by the arched culvert (030) above and is of described adequate capacity (as per Bob Pegnam).

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.



Photo ID: 037
Location: Miller Creek Wetland adjacent to Airport parking lot (Facing Northwest)
Description: Miller Creek D/S wetland culvert
Observations: Reportedly undersized[1] culvert w/riprap. Approximately 2' diameter.

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.



Photo ID: 038
Location: Miller Creek Wetland adjacent to Airport parking lot (Facing East)
Description: Miller Creek across Parking access road, U/S
Observations: Reportedly undersized[1] culvert with new bank stabilization implemented in the area. New plantings, woody debris present.

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.



Photo ID: 039
Location: Miller Creek Wetland adjacent to Airport parking lot (Facing East)
Description: Miller Creek across Parking access road, looking D/S
Observations: Reportedly undersized[1] culvert with new bank stabilization implemented in the area. New plantings, woody debris present.

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.





[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.

Photo ID: 040 and 041
Location: Miller Creek Wetland adjacent to Airport parking lot flow control structure (Facing East)
Description: Wetland portion west of Des Moines Drive.
Observations: Reportedly undersized[1] pipe coming into the structure, but the outlet culvert is not undersized, for most rain storms.



Photo ID: 050
Location: West of Des Moines Road, South of Miller Creek
Description: City of Burien Stormwater facility
Observations: Reportedly undersized[1] pipe into the birdcage structure for most rain storms. Overflow volumes are dealt with by a large vegetated detention area located south of the wetland and west of Des Moines Drive.

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.



Photo ID: 059
Location: East of SR-509, South of 136th Street
Description: WSDOT right of way at SR 509
Observations: Two 4-ft diameter, reportedly undersized[1] culverts. During rain events flood the 30-ft D/S easement and onto the property. Have been evaluated to initiate the flooding of the Miller Creek region, causing most severe of damage D/S. Water quality also an issue. Remnants from last oil spill present, and are a constant issue as to the environmental integrity of the wetland.

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.



Photo ID: 062
Location: S 140th St and 8th Ave
Description: Looking North at 8th Ave
Observations: Catchbasin at 8th Ave. takes runoff from road North. No offsite drainage west of 8th Ave.

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.



Photo ID: 064
Location: S 140th St and 8th Ave
Description: Lookin East on 140th St
Observations: Curb and sidewalk on North side of 140th for half of the street length. South side has ditches with storm pipe (8").

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.



Photo ID: 068
Location: S 146th St and 8th Ave (Lookin East on 146th St)
Description: Looking East on 146th St
Observations: No curb or gutter, ditch by 8th Ave.

Location: Des Moines Drive
Description: Stretch of Des Moines length of project area
Observations: Before SR-518, Des Moines West side has curb, gutter. East sidewalk has a sidewalk at some portions. Newly paved road, catch basin storm data is not up to date with the improvements.

[1] As per conversation with Robert Pegnam, a property owner in Burien and resident of Bellevue.